

2607 Winston Rd.
Bethlehem, Pa. 18017
August 31, 1969

Bruce Sexton
2001 Lindell Rd.
Richmond, Va. 23235

Dear Bruce,

Model Rocketry Magazine forwarded your letter to me. I tried to contact you by phone when I was in your area two weeks ago, but you were not home.

In answer to your questions, I am afraid that the magazine artist who laid out the August article did a very poor job. He left the parts list off, and redrew the illustrations improperly.

The parts list is as follows:

Lo .570mh-2.80mh "Adj. r.f. coil" Miller no. 9003
Ca 100 pfd
Cb 3.0 mfd, 25v.d.c.
B1 22.5 volt battery, Burgess Y15
Battery Holder Lafayette no. 34H5005

All parts except battery holder are available from Burstein-Applebee, Kansas City, Missouri.

Figure 5 was supposed to indicate the use of a battery holder, and the semi-circle of wire at the top of the left-hand drawing was supposed to have been a mechanical support for the battery holder. The washer shown in figure 4 can be either metal or fiber.

I assume you understand that the accelerometer is designed to be plugged into the transmitter described in the May Issue. The

accelerometer does not operate by itself.

There is a correction to the May article which the magazine has not published yet. Inductor L2 should be a 10 uh. r.f. choke, Nytronics #SWD-10. It is available from Allied Radio, Chicago, Illinois.

Good luck with your project, and let me know how it works out.

Sincerely,

Richard Q. Fox

Richard Q. Fox